

DEPARTMENT OF ECOLOGY -- TOXICS CLEANUP PROGRAM  
INTEGRATED SITE INFORMATION SYSTEM  
UST INSPECTION SUMMARY AS OF 07/07/2009

UST SITE INFORMATION

SITE ID: 8827

SITE TAG # : A0269

SOUTH SERVICE CENTER

3613 4TH AVE S

SEATTLE, WA 98134

PHONE # : (206) 386-4577

UBI: 178-048-953 001 0085

FACILITY SITE INFORMATION

FACILITY SITE ID: 2171

SEATTLE CITY LIGHT SOUTH SERVICE CENTER

3613 4TH AVE S

SEATTLE, WA 98108

LATITUDE/LONGITUDE: 47° 34' 16.136"/-122° 19' 44.7060

SITE COMMENTS

4/7/06 aa- rec'd perm closure checklist for tanks six, four, five, three. 4/7/06 TD HQ REC'D NEW TANK INSTALLATION. 3/15/06 AA- Tanks ONE, TWO, & SEVEN are operational. 3/1/06 TD HQ SENT E MAIL TO WANDA FOR ONE NEW TANK TO BE REGISTERED W/DOL. 3/1/06 TD HQ MARKED TANKS ONE, TWO, THREE, FOUR, FIVE AND SIX REMOVED AS PER JOHN BAILS REQUEST VIA PARTIAL REPORT GIVEN. TANK 'SIX' IS REMOVED. IT IS TO BE REPLACED WITH NEW TANK. TANK 'FOUR', 'FIVE' AND 'THREE' ARE REMOVED & WILL NOT BE REPLACED. 30 DAY NOTICE MAY HAVE BEEN LACKING THESE ID #S. INFO FROM MIKE WEBB OF GARY STRUTHERS. REFER TO ERTS 551466 FOR MORE INFO. INITIAL RESULTS DO NOT INDICATE A NEW RELEASE. WAITING FOR CLEANUP REPORT TO DETERMINE IF NEW LISTING REQUIRED. [JMB,11/8/05]

INSPECTOR: OLSEN, RUSS

INSPECTION INFORMATION

INSPECTION TYPE: UST Compliance Inspection

INSPECTION METHOD: Field Visit

INSPECTION RESULT: Followup Required

INSPECTION DATE: 6/29/2006

INSPECTION CONTACT: MARY YODER WILLIAMS

SOC INSPECTION RESULTS

SOC SPILL/OVERFILL/CORROSION: Yes - In Compliance

SOC RELEASE DETECTION: Yes - In Compliance

INSPECTION COMMENTS

INSPECTOR: OLSEN, RUSS

INSPECTION INFORMATION

INSPECTION TYPE: UST Compliance Inspection

INSPECTION METHOD: Field Visit

INSPECTION RESULT: Followup Required

INSPECTION DATE: 6/29/2006

INSPECTION CONTACT: MARY YODER WILLIAMS

SOC INSPECTION RESULTS

SOC SPILL/OVERFILL/CORROSION: Yes - In Compliance

SOC RELEASE DETECTION: Yes - In Compliance

INSPECTION COMMENTS